

TECHNICAL & SAFETY COMMITTEE

INTERNATIONAL PARACHUTING COMMISSION (FAI)



Technical & Safety Information Notice No.	03/2010	W.N. 30
Date of Issue	09 August 2010	
Subject Matter and Applicability	<p>Note – The parachute systems in question are NOT sport parachuting rigs, but pilots' rigs. This Information Notice is being disseminated to inform Riggers who may be asked to repack one of these systems, and as a general guide to Riggers to be aware of this issue if it should appear at a future stage with a sport parachute system.</p> <p>PARACHUTES AUSTRALIA 22 Bosci Rd, Ingleburn NSW 2565 Australia (PO Box 969) Ph: + 61 2 98295355 Fax: +61 2 98291300 Email: sales@parachutesaustralia.com</p> <p>SERVICE BULLETIN No PA SB1001 Issued 9th August 2010</p> <p>SUBJECT: THINBACK AND SLIMPACK 2 RIPCORD HOUSING CLAMP</p> <p>STATUS: MANDATORY</p> <p>IDENTIFICATION: Thinback Harness & Container System Part No. S005-() manufactured between July 2009 and June 2010 serial numbers: 5036, 5037, 5038, 5039, 5040, 5041, 5042, 5043, 5044, 5056, 5057, 5058, 5059, 5060, 5087, 5088, 5089 and 5096 Slimpack 2 Harness & Container System Part No. S003 manufactured between April 2009 and April 2010 serial numbers: 673, 674, 675, 676, 677, 678, 679 and 680.</p> <p>BACKGROUND: At a scheduled 6 monthly inspection and repack of a Thinback Harness and Container System it was found that excessive force was required to pull the ripcord. Upon investigation it was discovered that the clamp that secures the ripcord housing located below the ripcord handle was loose allowing the housing to be extracted from its fabric cover when pulling the ripcord. Subsequent investigation revealed that during manufacture the housing clamp had been incorrectly installed onto the housing immediately below the housing end cap (refer image 1). The diameter of the housing is smaller than the minimum effective clamp range and should be installed around the housing's end cap (refer image 2).</p>	




Image 1




Image 2

MANUFACTURER ADVISORY:

Thinback and Slimpack 2 harness and container systems contained within the above mentioned serial numbers that has a housing clamp installed “below” the housing end cap are to be removed from service and returned to the manufacturer for rectification.

Effected equipment to be returned to Parachutes Australia are to be sent by Registered Post to the above address. The registered post cost will be refunded to the sender upon return of the equipment.

Thinback and Slimpack 2 harness and container systems contained within the above mentioned serial numbers that has a housing clamp installed on the housing end cap are unaffected and can remain in service.

AUTHORITY: Managing Director Underline Designs Pty Ltd trading as Parachutes Australia.

COMPLIANCE DATE: Immediate

DISTRIBUTION: Subscribers to the APF Service Bulletin Service Australian Gliding Federation

Compliance	Immediate and mandatory.
Concerned Publication	PARACHUTES AUSTRALIA SERVICE BULLETIN No PA SB1001 Issued 9th August 2010
Authority	Parachutes Australia
Acknowledgement	Thanks to Ms Kim Hardwick, Technical Officer, Australian Parachute Federation, for bringing Parachutes Australia Service Bulletin PA SB1001 to the notice of the Technical & Safety Committee.

	<p><i>Liam McNulty</i> IPC Technical & Safety Committee 09 August 2010</p>
--	--

Technical and Safety Information Notices issued by the Technical & Safety Committee of the International Parachuting Commission (FAI) are issued as information and help to parachuting nations and their affiliated members. The Information Notices are of an objective informative nature and there is no direct or implied criticism of any manufacturer or product intended. The Information Notices do not claim to be complete.

The Information Notices may result from:-

- 1 An incident or experience in the field being reported.**
- 2 A directive or notice issued by an aviation or government authority concerning parachuting operations or parachuting equipment.**
- 3 The issue of a notice by a manufacturer or by a National Parachuting Organisation.
In the case of equipment being the subject of the bulletin the reader is advised to check with the manufacturer regarding the current status or position of that equipment.**

Technical & Safety Committee of IPC, IPC and FAI accept no liability for the use or misuse of any information contained in this Information Notice. The reader assumes all liability.

<p>The Technical & Safety Committee, International Parachuting Commission, can be contacted on e-mail - lmcnulty@skydiveireland.ie</p>

<p>Liam McNulty, Technical & Safety Committee, International Parachuting Commission. 09 August 2010</p>
--